



# Release Notes for Catalyst 3560-CX and 2960-CX Series Switches, Cisco IOS Release 15.2(4)E and Later

---

**First Published: October 1, 2015**

**Last Updated: Apr 07, 2020**

This release note describes the features and caveats for the Cisco IOS Release 15.2(4)E software on the Catalyst 3560-CX and the Catalyst 2960-CX family of switches.

Verify that these release notes are correct for your switch:

- If you are installing a new switch, see the Cisco IOS release label on the rear panel of the switch.
- If your switch is on, use the **show version** privileged EXEC command. See the “[Upgrading the Switch Software](#)” section on page 4.
- If you are upgrading to a new release, see the software upgrade filename for the software version. See the “[Software Image](#)” section on page 5.

You can download the switch software from this site (registered Cisco.com users with a login password):

<http://www.cisco.com/download/navigator.html>

## Contents

- [Introduction](#), page 2
- [Supported Hardware](#), page 2
- [Device Manager System Requirements](#), page 3
- [Upgrading the Switch Software](#), page 4
- [Features of the Switch](#), page 5
- [New Software Features](#), page 7
- [Service and Support](#), page 9
- [Limitations and Restrictions](#), page 9



- [Caveats, page 10](#)
- [Related Documentation, page 16](#)

## Introduction

The Catalyst 3560-CX and Catalyst 2960-CX switches are compact Gigabit Ethernet (GE) switches that have features comparable to high-end Cisco switches but in smaller form factors. Some of the key features are:

- Up to 10 Gigabit uplinks for high-bandwidth applications and business growth
- Cisco Catalyst Instant Access mode (on 3560cx-12PD-S and 3560CX-8XPD-S switches) for management simplicity on switches with 10G uplink. See Instant Access FAQ [here](#).
- Support for Cisco Application Policy Infrastructure Controller Enterprise Module (APIC-EM) for software-defined networking (SDN) and programmability
- Integration with Cisco TrustSec® for identity, segmentation, and security
- Up to 240W of available power for PoE+ per switch — twice the available power of previous generation switches — for supporting more PoE devices
- Switch Hibernation Mode and Energy Efficient Ethernet (EEE) for lower energy costs
- NetFlow Lite for end to end visibility to the flows in the network

## Supported Hardware

### Switch Models

**Table 1** *Catalyst 3560-CX Switch Models*

Switch Model	Cisco IOS Image	Description
WS-C3560CX-8TC-S	IP Base IP Services	Non-PoE, 8 downlink ports, 8 access ports of 1G access ports, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G <sup>1</sup>
WS-C3560CX-8PC-S	IP Base IP Services	240W PoE+, 8 downlink ports, 8 access ports of 1G access ports, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G
WS-C3560CX-12TC-S	IP Base IP Services	Non-PoE, 12 downlink ports, 12 access ports of 1G, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G
WS-C3560CX-12PC-S	IP Base IP Services	240W PoE+, 12 downlink ports, 12 access ports of 1G, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G
WS-C3560CX-12PD-S	IP Base IP Services	240W PoE+, 12 downlink ports, 12 access ports of 1G, 2 SFP+ uplink ports of 10G, 2 uplink Cu ports of 1G

**Table 1** *Catalyst 3560-CX Switch Models (continued)*

Switch Model	Cisco IOS Image	Description
WS-C3560CX-8PT-S	IP Base IP Services	146W PoE+, 8 downlink ports, 8 access ports of 1G, 2 uplink UPoE+ ports of 1G
WS-C3560CX-8XPD-S	IP Base IP Services	240W PoE+, 8 downlink ports, 6 access ports of 1G, 2 access ports of 100M/1G/2.5G/5G/10G, 2 SFP+ uplink ports of 10G

1. For all switch models, the SFP ports and Cu ports are usable concurrently.

**Table 2** *Catalyst 2960-CX Switch Models*

Switch Model	Cisco IOS Image	Description
WS-C2960CX-8TC-L	LAN Base	Non-PoE, 8 downlink ports, 8 access ports of 1G, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G <sup>1</sup>
WS-C2960CX-8PC-L	LAN Base	124W PoE+, 8 downlink ports, 8 access ports of 1G, 2 SFP uplink ports of 1G, 2 uplink Cu ports of 1G

1. For all switch models, the SFP ports and Cu ports are usable concurrently.

## Optics Modules

The Catalyst 3560-CX and 2960-CX switches support a wide range of optics. Because the list of supported optics is updated on a regular basis, consult the tables at this URL for the latest SFP+ and SFP module compatibility information:

[http://www.cisco.com/en/US/products/hw/modules/ps5455/products\\_device\\_support\\_tables\\_list.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/products_device_support_tables_list.html)

# Device Manager System Requirements

## Hardware Requirements

**Table 3** *Minimum Hardware Requirements*

Processor Speed	DRAM	Number of Colors	Resolution	Font Size
233 MHz minimum <sup>1</sup>	512 MB <sup>2</sup>	256	1024 x 768	Small

1. We recommend 1 GHz.
2. We recommend 1 GB DRAM.

## Software Requirements

- Windows 2000, XP, Vista, Windows 7, and Windows Server 2003.

- Internet Explorer 6.0, 7.0, Firefox up to version 26.0 with JavaScript enabled.

## CNA Compatibility

For Cisco IOS Release 15.2(4)E, CNA support is available on release version 5.8.9 and later.

You can download Cisco Network Assistant from this URL:

<http://www.cisco.com/pcgi-bin/tablebuild.pl/NetworkAssistant>

For more information about Cisco Network Assistant, see the *Release Notes for Cisco Network Assistant* on Cisco.com.

# Upgrading the Switch Software

## Finding the Software Version and Feature Set

The Cisco IOS image is stored as a bin file in a directory that is named with the Cisco IOS release number. The files necessary for web management are contained in a subdirectory. The image is stored on the system board flash device (flash:).

You can use the **show version** privileged EXEC command to see the software version that is running on your switch.



---

**Note**

Although the **show version** output always shows the software image running on the switch, the model name shown at the end of this display is the factory configuration and does not change if you upgrade the software license.

---

You can also use the **dir filesystem:** privileged EXEC command to see the directory names of other software images that you might have stored in flash memory.

## Software Image

If you have a service support contract and order a software license or if you order a switch, you receive the universal software image and a specific software license.

**Table 4** *Software Image for Cisco Catalyst 3560-CX*

Image	Filename	Description
Universal image	c3560cx-universalk9-mz.152-4.E	IP Base and IP Services images.
Universal image	c3560cx-universalk9-tar.152-4.E	IP Base and IP Services cryptographic images with Device Manager.

**Table 5** *Software Image for Cisco Catalyst 2960-CX*

Image	Filename	Description
Universal image	c2960cx-universalk9-mz.152-4.E	LAN Base image.
Universal image	c2960cx-universalk9-tar.152-4.E	LAN Base cryptographic image with Device Manager.

## Features of the Switch

Cisco Catalyst 3560-CX switches features:

- PoE+ and non-PoE, 8 and 12 downlink ports, 1G SFP and 10G SFP+ uplink port models
- IPv4 and IPv6 routing, Multicast routing, advanced quality of service (QoS), and security features in hardware
- Cisco Catalyst Instant Access mode (on 3560cx-12PD-S and WS-C3560CX-8XPD-S switches) for management simplicity on switches with 10G uplink
- Up to 240W of available power for PoE+ per switch
- Switch Hibernation Mode and Energy Efficient Ethernet (EEE) for lower energy costs
- Horizontal Stacking (on WS-C3560CX-12PD-S and WS-3560CX-8XPD-S switches)
- Enhanced Limited Lifetime Warranty (E-LLW) with next business day (NBD) advance hardware replacement and 90 day access to Cisco Technical Assistance Center (TAC) support
- Enhanced Cisco EnergyWise for operational cost optimization by measuring actual power consumption of the PoE devices, reporting, and reducing energy consumption across the network
- USB Type-A and Type-B ports for storage and console respectively
- Application visibility and capacity planning with integrated NetFlow Lite
- Hardware support for Secure Group Access Control lists (SGACL) and IEEE 802.1AE MACsec.
- Software support for IEEE 802.1AE MACsec from Cisco IOS Release 15.2(4)E.

Cisco Catalyst 2960-CX switches features:

- PoE+ and non-PoE models, 8 downlink ports, 1G SFP uplink port models
- Reduced power consumption and advanced energy management features
- USB Type-A and Type-B ports for storage and console respectively
- Application visibility and capacity planning with integrated NetFlow Lite

- Switch Hibernation Mode and Energy Efficient Ethernet (EEE) for lower energy costs
- Enhanced Limited Lifetime Warranty (E-LLW) with next business day (NBD) advance hardware replacement and 90 day access to Cisco Technical Assistance Center (TAC) support
- Enhanced Cisco EnergyWise for operational cost optimization by measuring actual power consumption of the PoE devices, reporting, and reducing energy consumption across the network

## New Software Features

- [Features Introduced in Cisco IOS Release 15.2\(4\)E10, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E9, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E8, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E7, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E6, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E5, page 7](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E4, page 8](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E3, page 8](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E2, page 8](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E1, page 8](#)
- [Features Introduced in Cisco IOS Release 15.2\(4\)E, page 8](#)

### Features Introduced in Cisco IOS Release 15.2(4)E10

There are no new features in this release.

### Features Introduced in Cisco IOS Release 15.2(4)E9

There are no new features in this release.

### Features Introduced in Cisco IOS Release 15.2(4)E8

- There are no new features in this release.

### Features Introduced in Cisco IOS Release 15.2(4)E7

- There are no new features in this release.

### Features Introduced in Cisco IOS Release 15.2(4)E6

- There are no new features in this release.

### Features Introduced in Cisco IOS Release 15.2(4)E5

- There are no new features in this release.

## Features Introduced in Cisco IOS Release 15.2(4)E4

There are no new features in this release.

## Features Introduced in Cisco IOS Release 15.2(4)E3

There are no new features in this release.

## Features Introduced in Cisco IOS Release 15.2(4)E2

- EtherChannel Load Deferral: In an Instant Access system, the EtherChannel Load Deferral feature allows ports to be bundled into port channels, but prevents the assignment of group mask values to these ports. This prevents the traffic from being forwarded to new instant access stack members and reduce data loss following a stateful switchover (SSO).
- Cisco S-Class Optics Support on Cisco Catalyst 3560-CX Series Switches: The following S-Class Optics are supported:
  - SFP-10G-SR-S
  - SFP-10G-ZR-S
  - SFP-10G-ER-S
  - SFP-10G-LR-S

## Features Introduced in Cisco IOS Release 15.2(4)E1

- (LAN Lite, IP Base, LAN Base) 2 Event Classification: This feature helps discover the power requirements of PoE-powered devices before LLDP negotiation starts.
- (LAN Lite, IP Base, LAN Base) Fast Power over Ethernet (PoE): After a power outage, when power is restored, PoE to the endpoints on switch ports are restored quickly
- (IP Base, LAN Base) Security Group Tag Over SGT Exchange Protocol (SXP): SGT Exchange Protocol (SXP) propagates the Security Group Tags (SGTs) across network devices that do not have hardware support for Cisco TrustSec. SGACL support is also available in this release for Catalyst 3560-CX switches.
- Limiting Login: The Limiting Login feature helps network administrators to limit the login attempt of users to a network. When a user fails to successfully login to a network within a configurable number of attempts within a configurable time limit, the user can be blocked. This feature is enabled only for local users and not for remote users. You need to configure the **aaa authentication rejected** command in global configuration mode to enable this feature.
- x.509v3 with SSH Authentication: This feature uses the public key algorithm (PKI) for server and user authentication, and allows the Secure Shell (SSH) protocol to verify the identity of the owner of a key pair via digital certificates, signed and issued by a Certificate Authority (CA).

## Features Introduced in Cisco IOS Release 15.2(4)E

- (LAN Base, IP Base, IP Services) New enhancements like LACP rate fast, min links, LACP over QinQ (L2PT LACP) are added.



- Named VLAN: Option to specify a VLAN name for access and voice VLAN.
- Switches that support 10G SFP+ uplink ports (with optical cables) and MGig ports (on copper cables) can now be a part of Horizontal Stacking.
- (LAN Base) Control Plane Policing (CoPP) feature runs on a predefined set of protocols to control the flow of traffic coming to the CPU based on a defined rate limit on specific protocol packets. The CoPP protects the CPU from denial of service (DoS) attacks and ensures routing stability, reachability, and packet delivery.
- Rapid PVST+: Rapid PVST+ is now the default spanning-tree mode used on all Ethernet port-based VLANs.
- (Catalyst 3560-CX switches) The Auto Identity feature provides a set of built-in policies at the global configuration and interface configuration modes. The Auto Identity feature use the Cisco Common Classification Policy Language (C3PL)-based configuration that significantly reduces the number of commands used to configure both authentication methods and interface-level commands. The Auto Identity feature provides a set of builtin policies that are based on policy maps, class maps, parameter maps, and interface templates.
- Cisco TrustSec NDAC MACsec: MACsec link layer switch-to-switch security by using Cisco TrustSec Network Device Admission Control (NDAC) and the Security Association Protocol (SAP) key exchange
- MKA MACsec encryption: 802.1AE MACsec encryption with MACsec Key Agreement (MKA) on downlink ports for encryption between the switch and host devices.

## Service and Support

### Information About Caveats

If you need information about a specific caveat that does not appear in these release notes, you can use the Cisco Bug Toolkit to find caveats of any severity. Click this URL to browse to the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolKit/>

If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.

### Troubleshooting

For the most up-to-date, detailed troubleshooting information, see the Cisco TAC website at this URL:

<http://www.cisco.com/en/US/support/index.html>

Click **Product Support** > **Switches**. Choose your product and click **Troubleshooting** to find information on the problem you are experiencing.

## Limitations and Restrictions

- Effective with Cisco IOS Release 15.2(4)E5, Smart Install feature is not available in Cisco IOS software.

- When a logging discriminator is configured and applied to a device, memory leak is seen under heavy syslog or debug output. The rate of the leak is dependent on the quantity of logs produced. In extreme cases, the device may crash. As a workaround, disable the logging discriminator on the device.
- Standalone web-based authentication fails if the switch port is configured without any port ACL. (CSCuu91975)

## Caveats

- [Cisco Bug Search Tool](#), page 10
- [Open Caveats](#), page 10
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E10](#), page 11
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E9](#), page 12
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E8](#), page 12
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E7](#), page 12
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E6](#), page 14
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E5](#), page 14
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E4](#), page 14
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E3](#), page 14
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E2](#), page 15
- [Caveats Resolved in Cisco IOS Release 15.2\(4\)E](#), page 15

## Cisco Bug Search Tool

The Bug Search Tool (BST), which is the online successor to Bug Toolkit, is designed to improve the effectiveness in network risk management and device troubleshooting. The BST allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat listed in this document:

1. Access the BST (use your Cisco user ID and password) at <https://tools.cisco.com/bugsearch/>.
2. Enter the bug ID in the **Search For:** field.

## Open Caveats

Bug ID	Headline
CSCva26201	3750X is not sending correct DSCP value in cflow IP header.
CSCvk21769	C2960L packet loss on 10M/Full port.

<a href="#">CSCvk38377</a>	C4K_SNIPSMAN-3-GTXRXRESETFAILURE: Gtx Rx Reset Error in Snips.
<a href="#">CSCvm36476</a>	C2960 plus handling GARP unexpectedly.
<a href="#">CSCvm24330</a>	Tracebacks seen on loadversion due to MTU mismatch.
<a href="#">CSCvo37003</a>	C4500 not showing MAC add of device (Avaya phone) in "show mac add" table after enabling mab,dot1x.
<a href="#">CSCvo38680</a>	C6800IA-48FPD (FEX) reloads with a last reload reason of "Unknown reason".

## Caveats Resolved in Cisco IOS Release 15.2(4)E10

None.

## Caveats Resolved in Cisco IOS Release 15.2(4)E9

Bug ID	Headline
<a href="#">CSCvn72973</a>	Device is getting crashed on the "cts role-based enforcement"
<a href="#">CSCuv90519</a>	IKEv2 session fails to come up after tunnel source address change
<a href="#">CSCve21224</a>	ewlc: wncd crash seen at auth_mgr_pre_shim_handle_pre_event
<a href="#">CSCve57810</a>	Device failing over without 'fail next-method' or 'no-response next method'
<a href="#">CSCvj23301</a>	IOS: Crypto Ruleset fails to get deleted
<a href="#">CSCvk56331</a>	Initial contact in IKEv1 phase 2 rekey (QM1) causes all crypto sessions to drop
<a href="#">CSCvn13735</a>	Failure to detect the back to back CoA requests, leading to policy deletion.
<a href="#">CSCvn00129</a>	After CoA push from ISE, Result of "show cts policy sgt" has multiple policies for "to unknown"
<a href="#">CSCvp76403</a>	Defaulting interface config on dot1x interface results in incorrect port-control state on port

## Caveats Resolved in Cisco IOS Release 15.2(4)E8

Bug ID	Headline
<a href="#">CSCvc71220</a>	Fix the quotes issue in SA build infra
<a href="#">CSCve89361</a>	Crash in SISF while processing IPv6 packet
<a href="#">CSCvj86626</a>	Clients stuck in authentication loop when interface template is pushed from Radius server
<a href="#">CSCvk62735</a>	3750   high CPU   HAACL Acl Manager
<a href="#">CSCvm43071</a>	[IBNS 2.0] aaa-available event is not being triggered when using authentication/authorization list
<a href="#">CSCvm52157</a>	Cat4K/sup8-E VSS 3.8.5aE- running out of CPU and IO memory resources while clearing access-session

## Caveats Resolved in Cisco IOS Release 15.2(4)E7

Bug ID	Headline
<a href="#">CSCva10393</a>	System crashed during boot up on 4948E.
<a href="#">CSCvd87317</a>	The <b>ip access-list logging hash-generation</b> command not function expectedly.
<a href="#">CSCve37498</a>	Switch sends duplicate accounting message, that causing ISE to generate misconfigured NAS Alarms.
<a href="#">CSCve69049</a>	Crash when it tries to write over a TTY session.
<a href="#">CSCve73467</a>	Link not up on M-gig line cards WS-X4748-12X48U+E with cable length of 300Ft.
<a href="#">CSCvg82674</a>	VSS Standby crashes @ /k5/aclman/K5AclProfileMapEntry.cxx:135

<a href="#">CSCvh28285</a>	H/W mac address table learn wrong mac address on C4500X VSS with Flexlink switchover.
<a href="#">CSCvh79168</a>	Crash on numPolicersPerBank with Invalid policerBaseIndex.
<a href="#">CSCvh89534</a>	4500 Sup 8E DACL applied to the incorrect interface.
<a href="#">CSCvi01706</a>	Removing ACE from long ACL interrupts traffic.
<a href="#">CSCvi25365</a>	2960x - session to the member switch fails in stack.
<a href="#">CSCvi50136</a>	Repeated Modification of ACL causes standby switch to crash.
<a href="#">CSCvj29126</a>	RADIUS client on network fails to solicit PAC key from Cisco TrustSec even though the device has a valid PAC.
<a href="#">CSCvj41439</a>	ACL TCAM USAGE is different when using the same ACL configuration but different IOS version.
<a href="#">CSCvk23596</a>	Additional fix needed for CSCvg34881 (Catalyst 4500 crash when WS-X4748 card goes down).
<a href="#">CSCvk52487</a>	3750X Switch crash due to memory leak in HL2MCM process.

## Caveats Resolved in Cisco IOS Release 15.2(4)E6

Bug ID	Headline
<a href="#">CSCvd40673</a>	Cisco Smart Install Denial of Service Vulnerability.
<a href="#">CSCvf96579</a>	Catalyst 2960 Series Swtiches :AAARadius authentication fails with <b>switchport voice vlan dot1p</b> command.
<a href="#">CSCvg70852</a>	Unknown MAC addresses appear on port when trying to authenticate using dot1x.
<a href="#">CSCvg97016</a>	Memory Leak with IPDT [IP Device Tracking].

## Caveats Resolved in Cisco IOS Release 15.2(4)E5

Bug ID	Headline
<a href="#">CSCva86436</a>	No export ipv4 unicast map triggered router to crash.
<a href="#">CSCvc72751</a>	Endpoint bypasses restriction given by ISE and gets network access.
<a href="#">CSCuz61109</a>	Self ping to port channel subinterface dropped with LISP decap log.
<a href="#">CSCuz94245</a>	IGP-LDP sync interoperability for OSPF multiarea adjacency.
<a href="#">CSCuz95753</a>	Paramiko SSH client, having password authentication, fails to connect to IOS.

## Caveats Resolved in Cisco IOS Release 15.2(4)E4

Bug ID	Headline
<a href="#">CSCun71347</a>	3850 Crash in "CEF: IPv4" Process While Processing ARP Throttle Elements
<a href="#">CSCuq91509</a>	2960X/XR : Hibernation can not be configured for overnight period
<a href="#">CSCux05246</a>	snmpwalk and snmpget have incorrect behavior on IP SLA
<a href="#">CSCuz28618</a>	sup2t: sup crashed after MFIB errors
<a href="#">CSCva45821</a>	IOS switch does not update native VLAN in LLDP
<a href="#">CSCvb47673</a>	(3560-CX) SYS-2-MALLOCFAIL- Traceback and Crash observed in 2k stack
<a href="#">CSCvb91425</a>	(3560-CX) Output drops increased after enabling PIM on VLAN
<a href="#">CSCvc03727</a>	IPDT host tracking max limit doesn't work correctly
<a href="#">CSCvc84352</a>	IP Phone connectivity loss with dynamically assigned vlan and MDA

## Caveats Resolved in Cisco IOS Release 15.2(4)E3

There are no resolved caveats in this release.

## Caveats Resolved in Cisco IOS Release 15.2(4)E2

Bug ID	Headline
<a href="#">CSCur64110</a>	Queue-based Transmit/Drop QoS counters for Cisco Catalyst 4000 Series Switches.
<a href="#">CSCuu66503</a>	HTTPs: IOS HTTPS client not enforcing subject-name verification.
<a href="#">CSCuv27265</a>	ENH: Enable support for TLSv1.1 & TLSv1.2 for HTTP secure server/client.
<a href="#">CSCuv41355</a>	Unable to telnet: No wild listener: port 23.
<a href="#">CSCuv92875</a>	Add prefix information in IPv6 RA when system/ SVI is shutdown.
<a href="#">CSCuw36080</a>	SNMP with extended ACL.
<a href="#">CSCuw48118</a>	Cisco ASR 920 Series switches: crash in bcopy called from addnew during reassembly.
<a href="#">CSCuw49406</a>	“no ip routing protocol purge interface” delete with reload
<a href="#">CSCux26097</a>	Debug logging - parser issue.
<a href="#">CSCux38417</a>	Cisco IOS and IOS-XE IKEv2 fragmentation DoS.
<a href="#">CSCux85039</a>	Cisco Catalyst 3650 and 3850 Series Switches: Syslog produces no output when set to logging queue-limit X.
<a href="#">CSCux99025</a>	Evaluation of Cisco IOS and IOS-XE for NTP January 2016.
<a href="#">CSCux99594</a>	EEM policies may not be able to send emails.
<a href="#">CSCuy03680</a>	V3Lite IGMP packets sent instead of V3 when UDP based feature is present.
<a href="#">CSCuy05927</a>	IPC-WATERMARK and CHKPT-5-HIGHBUFFER logs leading to reload.
<a href="#">CSCuy12271</a>	Wrong LSP size calculation following MAC move with OTV.
<a href="#">CSCuy43392</a>	Cisco 5760 Wireless LAN Controller crash at snmp_subagent.
<a href="#">CSCuy44377</a>	Syslog: Source-Interface address change does not take effect in IPv6.
<a href="#">CSCuy87667</a>	Crash due to block overrun by AAA banner.
<a href="#">CSCuy92281</a>	VLAN 1 interface is shutdown during bootup.
<a href="#">CSCuz52528</a>	Evaluation of all for OpenSSL May 2016.
<a href="#">CSCuz02766</a>	Crash in IOSd with ‘EPC SM Liaison Update proc’.
<a href="#">CSCud37408</a>	PerfMon entries not idle timing out.

## Caveats Resolved in Cisco IOS Release 15.2(4)E

Bug ID	Headline
<a href="#">CSCus13924</a>	Device crashes while configuring 'Identity' commands
<a href="#">CSCuu69332</a>	(Catalyst 3560-CX Switches) Frame with special DesMac is forwarded by STP block port

Bug ID	Headline
CSCuu83085	Memory leaks @ AAA Account Response.
CSCuu92224	2960X - EPM vlan plugin crash

## Related Documentation

- Catalyst 3560-CX and Catalyst 2960-CX switch documentation at these URLs:  
<http://www.cisco.com/c/en/us/support/switches/catalyst-2960-cx-series-switches/tsd-products-support-series-home.html>  
<http://www.cisco.com/c/en/us/support/switches/catalyst-3560-cx-series-switches/tsd-products-support-series-home.html>
- Cisco SFP and SFP+ modules documentation, including compatibility matrices at this URL:  
[http://www.cisco.com/en/US/products/hw/modules/ps5455/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/tsd_products_support_series_home.html)
- Cisco Validated Designs documents at this URL:  
<http://www.cisco.com/go/designzone>

## Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco Marketplace](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

## Cisco Bug Search Tool

**Cisco Bug Search Tool** (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

This document is to be used in conjunction with the documents listed in the "Notices" section.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2015-2019 Cisco Systems, Inc. All rights reserved.